



1/28




Fig. 1

2/28




Fig. 2

3/28




Fig. 3




Fig. 4

5/28




Fig. 5

6/28




Fig. 6




Fig. 7

7/28




Fig. 8




Fig. 9



8/28





Fig. 10

9/28



- ☒ Etch Area to .007" .001"
- ☒ Through Holes
- ☐ Not Etched

Fig. 11a




Fig. 11b

10/28




Fig. 12a




Fig. 12b

11/28




Fig. 13a




Fig. 13b

12/28




Fig. 14a




Fig. 14b

13/28




Fig. 14c




Fig. 14d

14/28




Fig. 15a

15/28




Fig. 15b




Fig. 15c

Fig. 15d

17/28




Fig. 15e

18/28

Exergy Balance
 (All values in watts)

- ☒ Chemical Exergy
- ☒ Physical Exergy




Fig. 16a

19 / 28




Fig. 16b

20/28




Fig. 16c

21/28




Fig. 16d

22/28




Fig. 16e

23/28

Enthalpy Balance
(All values in watts)

Chemical Enthalpy
Physical Enthalpy




Fig. 17a

24/28




Fig. 17b

25/28




Fig. 17c

26/28




Fig. 17d

27/28




Fig. 17e

28/28




Fig. 18